## Annexure D

## BUILDING SAFETY CERTIFICATE

No. 89				Date	d: 91 07 202	2	
It is certified that the ex	isting buildir	ng Asign	Mosld	School	(name of	the	150
building or premises) at .1							
(add	lress) is hav	ing block(s)/Flo	oor(s) as per	details below:			
Detail of Block(s) in	Block	Block	Block	Block	Block	Block	
school	(1)	(2)	(3)	(4)	(5)	(6)	
No. of Floor(s) in the	2. G1+						_
Block	4. G+ 3						
The building is owned/occupied by Asian Liord School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D. Jailux (Name of Department/ Govt.) on 30.6.2025 (date of inspection) in the presence of Sanday Godina Secondary (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 11.06.24 for a period of 23 years in accordance with rule and subject to compliance of the specific conditions as appended.  1. 2. 3. 4. Revised on 01.07.2025							
* Strike out whichever is no detail.	ot applicable	e. In case of b		e with Seal :	DEEKSHA ASI	ARWAL 3HUAL	
Joan		Name	& Address	of Department/		ग् <u>ड शिक्षा</u> द	Ber.

